

FIG. 2




FIG.3

1,1	1,2	1,3
2,1	2,2	2,3
3,1	3,2	3,3

FIG.4

,P	2	1
-1	-2	-1
0	0	0

FIG.5A


0	0	0	
,Р	2	1	
-1	-2	-1	
FIG 5B			

1	-1	0
2	-2	0
1	-1	0


FIG.5C

0	1	-1
0	2	-2
Į <b>O</b>	1	-1

FIG.5D



**FIG.** 6



**FIG.** 7




FIG. 8




FIG. 9




FIG. 10

1,1	1,2	1,3	1,4	1,5
2,1	2,2	2,3	2,4	2,5
3,1	3,2	3,3	3,4	3,5
4,1	4,2	4,3	4,4	4,5
5,1	5,2	5,3	5,4	5,5

FIG.11

0	0	a <sub>13</sub>	a <sub>14</sub>	a <sub>15</sub>
0	0	a <sub>23</sub>	a <sub>24</sub>	a <sub>25</sub>
0	0	a <sub>33</sub>	a <sub>34</sub>	a <sub>35</sub>
0	0	a <sub>43</sub>	a <sub>44</sub>	a <sub>45</sub>
0	0	a <sub>53</sub>	a <sub>54</sub>	a <sub>55</sub>

FIG.12A

a <sub>11</sub>	a <sub>12</sub>	a <sub>13</sub>	a <sub>14</sub>	a <sub>15</sub>
0	a <sub>22</sub>	a <sub>23</sub>	a <sub>24</sub>	0
0	0	a <sub>33</sub>	0	0
0	0	0	0	0
0	0	0	0	0

FIG.12C

a <sub>11</sub>	a <sub>12</sub>	a <sub>13</sub>	a <sub>14</sub>	a <sub>15</sub>
0	a <sub>22</sub>	a <sub>23</sub>	a <sub>24</sub>	a <sub>25</sub>
0	0	a <sub>33</sub>	a <sub>34</sub>	a <sub>35</sub>
0	0	0	a <sub>44</sub>	a <sub>45</sub>
0	0	0	0	a <sub>55</sub>

FIG.12B

0	a <sub>12</sub>	a <sub>13</sub>	a <sub>14</sub>	0
0	a <sub>22</sub>	a <sub>23</sub>	a <sub>24</sub>	0
0	a <sub>32</sub>	a <sub>33</sub>	a <sub>34</sub>	0
0	a <sub>42</sub>	a <sub>43</sub>	a <sub>44</sub>	0
0	a <sub>52</sub>	a <sub>53</sub>	a <sub>54</sub>	0

FIG.12D




FIG.13